


# Revolving Lathe Centres

For accurate work holding in conventional or CNC lathes

| MODEL | MAXIMUM RUN-OUT |
|-------|-----------------|
| R-200 | 0,003 mm.       |
| R-300 | 0,003 mm.       |
| R-400 | 0,003 mm.       |
| R-500 | 0,004 mm.       |

| MODEL   | MORSE | LOAD FACTOR | SIZES mm. |    |    |    |    |     | WEIGHT |
|---------|-------|-------------|-----------|----|----|----|----|-----|--------|
| no.     | taper | kg.         | Ø1        | Ø2 | Ø3 | L1 | L2 | L3  | gr.    |
| R-200-N | 2     | 180         | 18        | 42 | -  | 24 | 35 | 128 | 430    |
| R-300-N | 3     | 400         | 22        | 49 | -  | 29 | 47 | 163 | 875    |
| R-400-N | 4     | 800         | 30        | 63 | -  | 35 | 52 | 196 | 1.505  |
| R-500-N | 5     | 1.750       | 33        | 85 | -  | 48 | 64 | 250 | 3.955  |
| R-300-C | 3     | 400         | 22        | 49 | 10 | 38 | 47 | 174 | 875    |
| R-400-C | 4     | 800         | 30        | 63 | 11 | 46 | 52 | 207 | 1.505  |
| R-500-C | 5     | 1.750       | 33        | 85 | 18 | 64 | 64 | 266 | 3.955  |
| R-300-H | 3     | 550         | 22        | 49 | -  | 47 | 47 | 163 | 905    |
| R-400-H | 4     | 900         | 24        | 63 | -  | 52 | 52 | 196 | 1.540  |
| R-500-H | 5     | 2.100       | 35        | 85 | -  | 64 | 64 | 250 | 4.035  |

Model N



Model C



Model H

